
"ACTIVE" SITE FORM



DISK #6

MICHIGAN DEPARTMENT OF NATURAL RESOURCES INTEROFFICE COMMUNICATION April 22, 1980 Kathy Morris, Water Quality District #1 TO: Jennifer Daniels, Groundwater Compliance & Special FROM: Section RE: Grand Trunk Western Railroad, Port Huron Diesel Fu Section 17, T6N, R17E, Port Huron Township, St. Clarr-co We apologize for the long delay in reviewing this hydrogeological study. With the recent expansion of this unit and completion of Phase I of the Groundwater Assessment Program, we hope to avoid such delays in

the future.

Due to several complaints of fuel losses and condition of the yard, Grand Trunk Western Railroad was requested to conduct a hydrogeological investigation. They retained Wade Trim & Associates, Inc. to perform the investigation and submitted the results of their Phase II hydrogeological investigation in July of 1979. (To my knowledge, Phase I was never submitted to the DNR). Phase II included the installation of 13 onsite borings to determine the direction of groundwater flow and hydrogeologic conditions of the site. Twelve of the thirteen borings were equiped with home-made Piezometers.

As we did not have the opportunity to review Phase I, I did a quick research on the hydrogeology of the area. Well logs as well as 13 onsite soil borings indicate the presence of a thin surficial layer of sand (0-10 feet thick) over laying a much thicker sequence of lake clays. The clay layer is 80 to 100 feet thick and appears to be laterally continuous across the site and the adjoining areas. Water supplies for the private wells in the area for which we have well logs are derived from relatively thin (10 to 30 feet thick) layers of sand and gravel which underlay the massive layer of clay. The majority of the people to the east and southeast of the site appear to be on municipal water supply.

I would like to make the following comments on Wade, Trim & Associates hydrogeological study.

- 1. The report indicates a perched surface aquifer in the surficial sand layer. The direction of groundwater flow is generally in an easterly direction, however, variations have shown a northwest and northeast component of flow.
- 2. I am uncertain as to why Wade Trim and Associates selected the locations they did for the piezometer/monitoring wells. Justification for their placement may have been given in Phase I which was not reviewed by this unit. Since the wells are located on the exterior of the property, it is possible that

the diesel fuel could leave the site, undetected, by traveling along the sewer lines. In addition, if a loss occurred and moved in an easterly direction, over 600' of aquifer would be contaminated before the diesel fuel reached monitoring well #3. Therefore, it may be beneficial to have some wells installed closer to areas of possible fuel losses and such that any contamination will be detected before it has a chance to enter or flow along the sewer system at the facility. This would greatly increase the detection before it moves off-site. Early detection of contamination makes clean-up operations easier and can be more cost effective to the company.

- 3. On page 4 of the report, it is stated that groundwater contamination has occurred from other activities on-site including a former dumping ground. The kind, level and extent of contamination should be looked into, especially due to a possible groundwater discharge into nearby ditches as indicated on page 5 of the report.
- 4. The Wade Trim and Associates Phase II study does not show any significant contamination on-site. As lab samples have only been run once, you may want to request additional sampling. Especially in respect to well number 1 which indicated 2 ppm oil and grease..
- 5. Routine inspection of the wells installed should be completed by the company. If you feel that there is chance that some contamination has occurred and moved off-site, you may want to request that some monitoring wells be installed down gradient. Even though the data does not indicate any significant groundwater contamination so far, it should be considered that there could be some on-site contamination that has not reached any of the monitoring wells.

I hope this has addressed your concerns about this facility. If I may be of any further assistance, please feel free to contact me at 517/373-2794.

ma
cc: R. Kimmel
Files

v

PHONE CONVERSATION

REP IS AT B WASTE DISPOSAL MEDOSOSTROSS

•	Mæ0050599075
DATE 5/10/85	TDD # ROS-8303-03C
TIME 11:30 AM	Page
SITE A + B WASTE	DISPOSAL
CONTACT LEONARD GOSS	PHONE (313) 987 - 6000
SUPERINTENDENT	<u> </u>
PORTINEON CITY	MATER DEPT.
SUBJECT: PORT HURDA MI	UNICIPAL WATER SYSTEM - BOUNDRIES
MR. GOSS STATED	THE CITY OF PORT HUROW IS
THE MAIN SERVICE AREA.	THERE ARE SOME RESIDENCES
JUST OUTSIDE THE ACTUAL	L CITY LIMITS THAT ARE ON
THE MUNICIPAL SYSTEM	BUT THIS SERVICE TENDS TO
BE SPOTTY: THE CITY D	DES RUN ADO INCH MAIN ALONG
GRISWOLD ROAD OUT TO	THE CITY OF SPARLINGVILLE,
(RANGE RD.). THERE ARE	NO PLANS AT THIS TIME TO
EXPAND THE PRESENT	SYSTEM, ALSO, ANY SUCH
EXPANSION WOULD BE	COSTLY.

Scoth dreen Deta: 5/10/85

Port Huron Township
Beil => Elaine Graffen Plain * Patrac 1 MI. Johnson + anderson 313-334-9901 11/19/87 Mr. Brainer - watermain Grant well send water main enformation for Southern 1/2 af Part Huron.

fear Jep.

Sparlinguil

*

West bornely; Range Rep 11 - Thousach

Part Herron Lugar 1/3
John Mercurio - meta Craw

+ 656

313-987-6000

* Januarship 87-6600 Elaine

levendry for mun well Depter ? = 35,000 City

3 townsh

people on privile week?

Fort Hasha 385-4489 Dwain Geoskey

Orainage Olitas?

Kimbell 987-9797 Many

Kimball Lup >> Waters tup Population Potentially Appetled
by Counce Trank Red Diesel spill

80% × 1254/mi2 = 1003.2

20% × 189/mi2 = 37,8

1041 for /mi2

ist a 29 of Company for the

4 mile radius!

75% × 1254/m² = 940.5

20 10 × 189/m² = 37.8

5% × 106/m² = 5.3

983.6 pt/m²

arille 983.6 × 52.3 - 49.376 people

1 mule radins.

90% x 12.54 /m² = 1128.6

10% x 189/m² = 18.9

1147.5

11475 x 3.14 = 3603 parple

i IT

Site Name	Grave	Trunk Ro	uloras	
County				

CALL LOG

1) Verify site location and size.

2) Verify & and size of each containment structure.

3) Is there existing exposure of people documented?

4) Is the site fenced? Is it secure?

5) If sampling was done, how were samples collected? i.e. random, selective, surface grab, composite etc.

6) Has the fire marshall considered the site a fire hazard?

) What type of companies used the site? (Origin of chemicals)

DATE

AGENCY

PHONE NUMBER

PERSON CONTACTED

7/14/86 site is not on Cerclis, and is not a RCRA facility

Barry C

Site Name	for son of	Trusk PR.	
County	<u> 80-</u>	dare (°	

PERSON CONTACTED

CALL LOG

1) Verify Site Location and Size.

2) Verify # and size of each containment structure.

3) Is there existing exposure of people documented?

4) Is the site fenced? Is it secure?

5) If sampling was done, how were samples collected? i.e. random selective, surface grab, composite etc..

6) Has the fire marshall considered the site a fire hazard?

7) What type of companies used the site? (Origin of chemicals)


-8-86 (its of Port Huran (313)987-6000 Dan Collins


2 major spulls Mar 13'78 Feb 7'79 broken dehvery

lies of 72 fuel oil. Sent to Servage lift Staton.

Mostly intained there but some in 79 went to 1° trasmet area. No other spills some them. Dil was coming in the N'81 but this thus tricked off to nothing. They even stopped monitoring that station for oil. ** Restabled are oil-water Separator in cath basin. For the most part this has worked to stop with.

Prepared by: ______







Grand Trunk Western Railroad Co

131 West Lafayette Boulevard Detroit. Michigan 48226

February 27, 1979 File: X 12-5 Pt. Huron

Mr. Roy E. Schrameck, District Engineer Water Quality Division
Department of Natural Resources
Route #2
Rockwood, Michigan 48173

Attention: Mr. William E. Stone

Re: Project No. 230/0327, Port Huron Pollution

Dear Mr. Schrameck:

Reference your letter of October 16, 1979 outlining conditions to be investigated which required the services of outside consultants.

Wade, Trim & Associates have completed their Phase I investigation to determine the optimum method of proceeding to obtain the required data. Copy attached.

We have now entered into a Phase II Agreement with Wade, Trim & Associates to develop the final report along the line of their February 16, 1979 letter (copy attached). It will be noted that they expect ground conditions for investigation to have improved sufficiently by late March to permit boring, etc.

Trusting this letter meets your immediate requirements as to our progress.

Very truly yours,

Ř. P. Cornwell Chief Engineer

Attachments

MAR 01 1979

PTE MOUILLEE S.G.A.

BUREAU OF WATER MANAGEMENT AND

WATER RESOURCES COMMISSION

Memorandum

To:

Files

Cathy Morse

Date:

From:

June 25, 1979

Subject Grand Trunk Railroad

Det. Eng. Office

Groundwater Study at

Port Huron Terminal

Spoke to one of the engineers, not Mr. Veitch, and was advised that Wade, Trim & Associates were or nearly completed with the groundwater study at the Port Huron Terminal as of this date.

cc: Cathy Morse

BUREAU OF WATER MANAGEMENT

AND

WATER RESOURCES COMMISSION

Memorandum

To:

Files

From:

Cathy Morse

Date:

June 25, 1979

Subject City of Port Huron, Dan Collins

√Grand Trunk Railroad

Groundwater Study

Informed Mr. Fred Kemp, of the same office, that the groundwater study is or is nearly completed at G.T.R.R., Port Huron Terminal. I advised Mr. Kemp that I will speak with Mr. Collins again, after learning more on the subject, at a later date, from Mr. Veitch.

cc: C. Morse

Sheek of Janes De Salva Janes Sunson and Janes her growned from for



131 West Lafayette Boulevard Detroit, Michigan 48226

August 28, 1979

File: X 12-5 Pt, Huron

(H) (D)

Ms. Kathy Morse
Water Quality Division
Department of Natural Resources
Route #2
Rockwood, MI 48173

Re: Project No. 230/0327, Port Huron Pollution, Phase II Groundwater Contamination Study - Port Huron Diesel Fueling Facility

Dear Ms. Morse:

Attached for your use and records are two copies of Wade, Trim & Associates' final report on subject project. Conclusions contained on Pages 5 & 6 are closely aligned to the items listed in my letter of July 17, 1979.

Trusting the above is sufficient for your needs. I will await hearing from you.

Very truly yours,

D. Veitch


Bridge & Structure Engineer

Attachment

BECEIVED

AUG 3 0 1979

PTE. MOUILLEE S.G.A.



Civil Engineer. . Land Surveyors Planners

February 16, 1979

and Trunk Western Railroad Company 131 West Lafayette Boulevard, Room 903 Detroit, Michigan 48226

Attention: Mr. D. Veitch


Re: Proposal to Perform a Phase II
Groundwater Contamination Study
Port Huron, Michigan, Diesel Fueling Pacility

Dear Mr. Veitch:

In accordance with our January 22, 1979 letter, we are pleased to sur it our proposal for the Phase II Study at the Port Ruron acclity as outlined in our January, 1979, Phase I Ground at a Contamination Study Report to you.

The proposal includes the following items of work:

- 1. Installation of a network of piezometers at the site.
- Obtaining soil borings for soil character, classificatio, and quality analyses as part of the installation of the piezometers.
- Field survey and monitoring the piezometer installations to obtain the necessary field data to determine:
 - a. Existence and extent of any contaminated groundwater zone.
 - b. The direction of groundwater movement.
 - c. The approximate rate of movement.
 - d. The location or locations where discharges of oil occur to surface waters or into sewers.
 - Quantity of oil in the groundwater plume, if present.
 - f. The nature of the contamination.



- 4. An assessment of possible environmental and public health concerns based on the analysis of the field data.
- 7.5. Recommendations for containment of any groundwater con-

We propose to complete the Phase II Study and prepare a report for a fee not to exceed \$15,800 as outlined in the Phase I report, and we will bill on a time and material basis up to the fixed fee amount. If, however, during the course of the investigation because of any unknown or extenuating discoveries, circumstances, etc., which we feel will alter the course of the field investigation and possibly affect the project cost, we will advise you as soon as possible.

It is anticipated that the Phase II Study can begin in late March, 1979, or as soon as weather permits and the report will be completed within three months from the commencement of the field work.

Thank you for the opportunity to submit this proposal. If our proposal is acceptable, please sign both copies of the attached Contract Agreement and return the blue copy for our file.

Very truly yours,

WADE, TRIM & ASSOCIATES, INC.

M. L. Alexander

MLA:we ZZZ 1000-79 Enclosure

Wastewater Treatment Plant 100 Merchant Street January 16, 1979

Mr. William E. Stone Water Quality Division, DNR Pte. Mowillee State Game Area Rt. #2, Rockwood, Mi.

Dear Bill,

I am inquiring into the status of your progress with Grand Trunk Railroad in regard to their groundwater study which was required by Roy E. Schrameck through a letter written by yourself on October 16, 1978. The letter stated that the groundwater study should be completed by December 30, 1978.

We are interested in this study because we are experiencing a constant inflow of oil into one of our sewer pumping stations. We feel that the source of this oil is from the Grand Trunk Railroad / yard through infiltration of the sewer system. We have been experiencing this condition since March of 1978 when the oil spill at Grand Trunk occurred. This spill was mentioned in your letter.

For this reason we are interested in the groundwater study. We would like to know to what extent the oil has saturated the soil and an estimate of the volume of oil in the soil. This may give an indication as to the duration of infiltration we may expect to have.

Daniel L. Collins

Pollution Control Inspector

JANIT:

DLC:mah

L. Goss F. Kemp

XC:

PIE MULICE COM

ATURAL RESOURCES COMMISSION

LARE TOUCHNSON

FINE OF TALK
CHAIN PROCESSON

FILLING - SNELL
FILLING - MITTER

FORM - WOLFE

FILLING OF YOUNGLOVE

WILLIAM G. MILLIKEN Governor

DEPARTMENT OF NATURAL RESOURCES

STEVENS TIMASON BUILDING LANSING MICHIGAN 48920 HOWARD A TANNER DIRECTOR

Fig. Moullier State Game Area Rt. Wi, Rockwood, Mi 46192

Ostober 16, 1976

WATER RESOURCES COMMISSION

O WILL AM COLBURN
MATIN LENDE
CHARLEN D HARBIL
ULNAMON FILM
STANDER GLIACHENBURN
JOHN E WOLD
HELEN TWILLIE

CERTIFICE MAIL

C. H. Burgarin, President Drand Trum. Railroad room 800 131 W. Dafayette Detroit, Michigan

Dear Mr. Burdakin:

On September 20, 1978, members of my staff inspected the Grand Trunk Paill-road (C.T.R.k.) switching yard at 32nd and bancroft in Port Huron. The inspection was made in response to a pollution complaint filed with this office by an employee of the yard. The complaintant alleged that storm runoff from the yard, carrying oil and various chemicals, was reaching the St. Clair River via storm sewers and natural drains. Investigation revealed that both storm sewers that serve the yard are connected to the City of Fort Huron Wastewater Treatment Plant. Any runoff should receive adequate treatment at the plant therefore posing no threat to the river.

Although the runoff seems to present no problems, other areas of concern were realized from the investigation. Michigan Law, Part 5 Rules of General Rules of the Water Resources Commission promulgated under Act 245 of Public Acts of 1979 as amended, requires facilities having oil storage in excess of 40,000 gallon to develop a Pollution Incident Prevention Plan (PIPP). The switch yard, having a storage of at least 190,100 gallon of fuel oil, is subject to the law. Basically, the PIPP details the materials stored, the storage locations, volumes stored, and types of containment, such as diking. It also is a working plan outlining containment, notification and clean-up procedures in the event of a spill. The switch yard's PIFP would include emergency action to be taken in the event a tank car carrying toxic or nazardous materials exploded or ruptured within the yard.

Enclosed is a copy of Act 245, Part 5 Rules, a PIPP worksheet, and a critical materials list to aid in the preparation of the plan. The PIPP for the Port Huron switch yard must be submitted to Robert Courchaine, Chief Engineer, Water Quality Division, Department of Natural Resources, P. 0. box 30026, Lansing, MI 48909, by December 15, 1978 for approval. Please note that Part



5 Rules requires companies to immediately notify this emery of any spill brether to surface or groundwaters, or to sanitary or storm sewers. It also requires a written explanation of the rost within 10 days of its cooperance. It may be helpful to contait the United States proincemental Protection Agency, Grosse The orfice (315-676-6600) to determine towards spill provention plan requirements. It is possible both agency's 1-quirements could be patiented in one plan.

Another contern is possible ground contembration in the part or . We starf, adming their investigation, noticed that the adiage ggl in the part, adjectably around the refueling area and the switched, is naturated with cit.

They consulted with City of Fort Huren officials and were told that the most near had several oil losses. The most recent loss, this syring, being a close feel spill or well over 600 gallons. It is my starf's epicion, condition the sandy soil conditions in the area, that much of the oil has reasted to groundwater. Their opinion is supported by their observation to oil out the instead groundwater infiltrating the storm sewer that rund burth of the relability of the interest of the groundwater to the study should determine direction of flow, as but the storm water table, the aried extent of contamination, the degree or contain that we have been the types of oil involved. All spicy plan should be substitted to this of the completed of the contained as the completed of the compl

During their investigation, my staff noted two problems which are not within the jurisdiction of this department but were of such concern I fee! they should be brought to your attention. First, there were several piles if ratter grain along the tracks. These piles were producing a horrible stench and were attracting insects. The complaintant said that the yard workers often had to wade through the piles, a very unpleasant task. Removal of the grain would be in the best interests of both the railroad and its employees.

A potentially more hazardous situation is the condition of some of the tracks. The rails on at least two of the tracks had sunk into palast to a point where the top of the rail was level with the balast. The tracks in general seemed to be in poor condition and lacking in maintenance. My staff saw several tankers of vinyl chloride and propane gas in the yard. If these or any of the other numerous tankers carrying hazardous and toxic materials were to derail in the yard and rupture, human lives could be endangered or lost. Due to the seriousness of the situation, Grand Trunk Railroad should investigate the need for additional track maintenance at the Port Huron yard.

I would appreciate your prompt and personal attention to the matters discussed, and look forward to working with your staff in solving these problems. If you have any questions, feel free to contact me at (318) 379-9892.

Yours truly,

WATER QUALITY DIVISION

Roy E. Schrameck District Engineer

William E. Stone

Water Quality Division

RES:WES/jmg

cc: W. Bohunsky Fred Kemp V
Representative William Jowett V
William Turney
John Frenhan

T6N-RI7E-19 624' TGN- R-17E-7 109' T6N-17E - 7 Sand-4" TGN-R-17E 7 625' 121' 6251 TGN-R17E-7 Clay-Pan - 146' Drawl 161' TGN-R17E-7 Sand - 11', clay - 98', Sand - 115 T6N-RI7-E-18: clay 118 Sand 123 TGN-RI7E-18

			19	a sa a s
GEOLOGIA THURVEY SAMPLE No.				
0 3 1977	WATER \	WELL REC	CORD	MICHIGAN DEPARTMENT
LOCATION OF WELL	ACT 29	94 PA 196		OF PUBLIC HEALTH
TCLAIL FORTH	lum of	Fraction	E SW Section Numb	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
That inch And Direction from Road Intersections	47.21V	120132	Non-Responsive	6 N.S. 17 E.M.
on-Responsive				
Sk	etch Map:		4 WELL DEPTH: (completed)	1
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			5 Cable tool A	lotary Driven Dug
				tetted Bored :
				Air Conditioning Commercial
			Test Well	الطحال Height: Above/Bal
RHAME HOOD KA			7 CASING: Threaded We Diam.	Surfaceft.
2 FORMATION	THICKNESS	BOTTOM OF		epth Weight / his ft.
	STRATUM	STPATUM	8 SCREEN:	epth Drive Shoe? Yes No
SAND		52."	Type/ ALOSTIC Slot/Gauze /O	Dia.:
CLAY	108	110	Set between /// It, and	Lengthft.
	1.	///	Fittings:	1
GAS WIFINE SAND]	3" PULBEE	YACKER_
CLAY		116	ft. below land 10 PUMPING LEVEL below la	surface nd surface
MUDDY SAND	12	128'		rs. pumping 2 g.p.m.
			ft after b	rs, pumpingg.p.m.
			11 WATER QUALITY in Parts	
			Iron (Fe)C	hlorides (CI)
			HardnessO	ther
			12 WELL HEAD COMPLETION	t-mad
			13 Well Grouted / Yes	12" Above Grade
			Neat Cement Ber	ft. to <u>Top</u> ft.
				polition \(\frac{\frac}\fint{\fracc}\fir\f{\frac{\frac{\fracc}\frac{\frac{\frac{\frac{\frac{\frac{\frac}\f{\frac{\frac}
				Not installed
			Manufacturer's Name	MYERS (USED)
			Model Number 950 Length of Drop Pips 65	ft. capacity G.P.M.
			Type: Submersible	ft. capacity G.P.M. Reciprocating
			Jet	Reciprocating
16 Remarks, elevation, source of data, etc.		17 WATER V	VELL CONTRACTOR'S CERT	TEICATION:
Some Info by Driller, ITEM NO.		TINVELS!	Docks 485 Have and pello	ction and this report is true
CORRECTED BY		SSIR	TO GISTIOT HAT	REGISTRATION NO.
ELEVATION SY OF		Address	·	
DEPIH TO ROCK			1 G(Welson	Date 7-1-77
D67d 100M (Rev. 12-68)		Signed(<u>—</u>	AUTHORIZED REPRESENTATIVE	Uate / T / /

GEDLO CAL SURVEY SAMPLE NO.					
Who was a second	WATER Y	WELL REC	CORD		HIGAN DEPARTMENT OF PUBLIC HEALTH
County Township Name	11.00 1	Fraction	Se	ction Number Tow	n Number Range Number
Orst mee And Direction from Road Intersections	HUKAN		Non-Responsive		17 N'8! /7 E/W.
on-Responsive					
	Sketch Map:	=	I	(completed) Date	of Completion
			5 Cable tool	Rotary	Driven Dug
W			Hollow rod 6 USE: Domes	Jetted tic Public St	Bored
			lrrigati	on Air Cond	
	•		Test We 7 CASING: Three		, Height: Above/Below
1 MILE	THICKNESS	DECT. TO	Diam.	,	Surfaceft.
2 FORMATION	OF STRATUM	DEPTH TO BOTTOM OF STRATUM	in. to		WeightIbs./ft. Drive Shoe? Yes X No
() ()	90	91	8 SCREEN:		
0411			Stat (Grants)	19/1000 Dia	
Chag	92,	100'	Set between 📿	<u>5</u> ft. and <u>/0</u> /	ft.
GAS 4 GRAVEL	1+'	104	Fittings:	P. Pack	ON
CRAVEL 4/1/4/CR	5-1	109"	9 STATIC WATER I	EVEL below land surface	
10 70 200			10 PUMPING LEVE	L below land surfa	ce
			Life ft.	after <u>⊷∠</u> hrs. pump	ing g.p.m.
	,				ing g.p.m.
				'Y in Parts Per Milli Chlorides	
			12 WELL HEAD CO	OtherOther	n Approved Pit
			Pitles	s Adapter 1	
			13 Well Grouted?	Yes Z_No ent ☐ Bentonite	
			Depth: From_	ft. to	ft.
			50 feet 4	Direction	Type
			Well disinfected	d upon completion	,
			Manufacturer's	Name (DUL	\mathcal{O}
			Model Number	15405411	HP //2 Voirs //5
			Type: Subr	Pipeft.cap mersible	acityG.P.M.
			jet	Re	ciprocating
USE A 2ND SHEET IF NEEDED		17.00		2010 0507	
16 Remarks, elevation, source of data, etc.	200 July 1			DR'S CERTIFICAT my jurisdiction and	ION: I this report is true
IMPO. BY DRIFTER TEM NO.	V.	PEGIS	5640 Gratict TERST BUSINESS MA TERST BUSINESS MA	भितः — — — । भगागस्थः	C. 257
SOURRECTED BY:		Address	St. Clair, Mi	<i>(</i>	
e ADDITION BY		,	1	17/1/11	Sate 12-114-71
D67d 100M (Ruv. 12-68)		Signed <u></u> ≝	AUTHORIZED REPRES	ENTATIVE	-Date/ /-//


מבתו מתומנו מנים ומו בחוני

GEOLOGICA SURVEY SAMPLE No.		
	WATER WELL RE ACT 294 PA	1965 OF
1 LOCATION OF WELL		PUBLIC HEALTH
County Two Two Fort Ha	Fracti SW1	on Section No. Town Range (NE 1/4 NW) 7 6N N/S. 17E E/W.
Distance And Direction from Rood Intersections	OWNED	Non-Responsive
-Responsive	- · · · · · · ·	THE PROPERTY OF
2 FORMATION	THICKNESS DEPTI OF BOTTO STRATUM STRA	M OF
PO	- 1	- 1 5 🔀 Cable tool 🗌 Rotary 🗎 Driven 🔲 Dug
Janil .		Hollow rod Jetted Bored
Clare	8719	6 USE: Domestic Public Supply Industry Irrigation Air Conditioning Commercial
E 0 0 . 0	11/1/	Test Well
- Fare Same	. W.	7 CASING: Threaded Welded Height: Above/Below in. to 111th. Depth surface 11th.
ourse Land	1211	Weightlbs/ft.
		8 SCREEN:
		Type: Dia: 7
		Slot/Gauze 13 Length
		Set between 115 ft. and 115 ft.
		Fittings: 3" Calleyy on For
		9 STATIC WATER LEVEL
		10 PUMPING LEVEL below land surface
		50 ft. after hrs. pumping 1 g.p.m.
		ft. afterhrs. pumpingg.p.m.
		11 WATER QUALITY in Ports Per Million:
		Iron (Fe)Chlorides (CI)
·		Hardness
		12 WELL HEAD COMPLETION: In Approved Pit Pitless Adapter (A) 12" Above Grade
		13 GROUTING:
		Well Grouted? ☐ Yes ☒ No Material: ☐ Neat Cement ☐
		Depth: Fromft, toft,
		14 SANITARY: Nearest Source of possible contamination //
		feetDirectionType
		Well disinfected upon completion ☒ Yes ☐ No
		15 PUMP: Monutactor & Monda to the ringle that by
	V	Model Number
		Length of Drop Pipeft, capacityG.P.M. Type: Submersible
	1,7	☐ Jet ☐ Reciproceting
Remarks, elevation, source of data, etc.	Thi	TER WELL CONTRACTOR'S CERTIFICATION: s well was drilled under my jurisdiction and this report is true
ABBED INFO. BY DRILLING HEAD MUL	to t	he best of my knowledge and belief.
★CORRECTED BY:	We	REGISTERED BUSINESS NAME REGISTRATION NOT
· · · · · · · · · · · · · · · · · · ·	Ada	iress 5 6 40 Similar Rd. St.
**ADDITION BY: RS 2/2/167	. Sign	AUTHORIZED REPRESENTATIVE Date
67D 100M 6-66 PES 5 1967		AUTHOMIZED REPRESENTATIVE

EOLOGICAL SURVEY SAMPLE No.	REF 14	# 39	
FED 0.0	WATER		
LOCATION OF WELL	ACT 29	4 PA 196	PUBLIC HEALTH
ST CLAIR PORT HU	Pall	Fraction	Section Number Town Number Range Number 4 4 7 6 N%. /7 EX.
Pistance And Direction from Road Intersections			3 OWNER OF WELL:
-Responsive			
Locate with "X" in section below Sket	tch Map:		4 WELL DEPTH: (completed) Date of Completion
La puece			//3 ft.
,	300		Hollow rod Jetted Bored
	*		6 USE: Domestic Public Supply Industry Irrigation Air Conditioning Commercial
			Test Well
Howard LO.	+ 1		7 CASING: Threaded Welded Height: Above/Below Diam.
FORMATION	THICKNESS	DEPTH TO BOTTOM OF	4 in. to 110ft, Depth Weight 11 lbs./ft,
TORWATION	STRATUM	STRATUM	in, toft, Depth Drive Shoe? Yes No 8 SCREEN:
SAND	8'	811	Type: Stainless Dia.: 3"
CLAY	67'	15'	Slot/Gauze 12 Length 4.
•			Set between 09 ft. and 113 ft.
FINE SOND	3/	106	9 STATIC WATER LEVELY
FINE SAND COURSE SAND	1'	113'	ft. below land surface
	1		10 PUMPING LEVEL below land surface
	+		
			ft. after hrs. pumping g.p.m.
			11 WATER QUALITY in Parts Per Million: Iron (Fe) Chlorides (CI)
			12 WELL HEAD COMPLETION: In Approved Pit
			Pitless Adapter 2" Above Grade
·			13 Well Grouted? Yes No Neat Cement Bentonite
	-}		Depth: From
	-		1
			feetDirectionType Well disinfected upon completion Y Yes No
			15 PUMP: Not installed
			Manufacturer's Name HP Volts
	_	<u> </u>	Length of Drop Pipeft. capacityG.P.M.
		}	Type; Submersible Det Reciprocating
		<u> </u>	C sec. C recipiocating
USE A 2ND SHEET IF NEEDED 16 Remarks, elevation, source of data, etc.		17 WATER	WELL CONTRACTOR'S CERTIFICATION:
ADDED INFO BY DRILLER, ITEM NO.		This wel	I was drilled under my jurisdiction and this report is true est of my knowledge and belief.
*CORRECTED BY **ADDITION BY		REGIS	STERED BUSINESS NAME Drinking REGISTRATION NO.
ELEVATION			5640 Graziot Rd.
DEPTH TO ROCK			AUTHORIZED REPRESENTATIVE Date OC - 9-79
D67d 100M (Rev. 12-68)		j Signed <u>(</u>	AUTHORIZED REPRESENTATIVE
			Wiricar of the Dellin

REF 14 # 67 GEOLOGICAL SURVEY SAMPLE No. WATER WELL RECORD
ACT 294 PA 1965 MICHIGAN DEPARTMENT OF PUBLIC HEALTH LOCATION OF WELL Fraction Section Number Town Number Range Number Port Distance And Direction from Road Intersections 3 OWNER OF WELL: 4 WELL DEPTH: (completed) Date of Completion Sketch Map: 5 Deable tool Driven Rotary Dug Hollow rod Jetted 6 USE: Domestic Public Supply Irrigation. Air Conditioning Commercial Test Well 7 CASING: Threaded / Welded | Height: Above/Below Surface ____ft. THICKNESS DEPTH TO Weight _//_ lbs./ft. ft. Depth in, to **FORMATION** BOTTOM OF STRATUM STRATUM in. to ft. Depth Drive Shoe? Yes No 8 SCREEN: Set between // E ft. and//5 Fittings: 9 STATIC WATER LEVEL 40 ft. below land surface 10 PUMPING LEVEL below land surface 60 ft. after 6 hrs. pumping _ ft. after_ _ hrs. pumping _ 11 WATER QUALITY in Parts Per Million: Iron (Fe) _____ Chlorides (CI) _ Hardness _ _Other 12 WELL HEAD COMPLETION: In Approved Pit Diffess Adapter 12" Above Grade 13 Well Grouted? Yes No Neat Cement Bentonite _ft. to___ 14 Nearest Source of possible contamination 65 feet N-E Direction Well disinfected upon completion wes No Manufacturer's Name Not installed 15 PUMP: Model Number 15/4 HP Volts 1/5
Length of Drop Pipe 1/5 ft. capacity G.P.M. Type: Submersible ☐ Jet Reciprocating USE A 2ND SHEET IF NEEDED 16 Remarks, elevation, source of data, etc. 17 WATER WELL CONTRACTOR'S CERTIFICATION: This well was drilled under my jurisdiction and this report is true ADDED INFO BY DRILLER, ITEM NO. *CORNECTED BY * * ADDITION BY ELEVATION DEPTH TO ROCK D67d

GEOLOGICAL SURVEY SAMPLE No. RE	F14 #62
, —————	R WELL RECORD MICHIGAN DEPARTMENT
ACT	294 BA 1965 OF PUBLIC HEALTH
County C. R. Twp. T. T. T. T.	Fraction Section 40 Town Page (5)
t clair Finder	3 OWNER OF WELL
Distance And Direction from Road Intersections	3 OWNER OF WELL
2 FORMATION OF	
20	5 Cable tool Rotary Driven Dug
Clay //	Hollow rod Jetted Bored
line gradiel	6 USE: Domestic Public Supply Industry 123 Gustin Air Conditioning Commercial
from from	Test Well
	7 CASING: Threaded Welded Height: Above/Balow
	# in. to 123 ft. Depth surface ft. Weight lbs/ft.
	In. toft. Depth Drive Shoe? Yes \ No
	8 SCREEN:
	Type: W. W. Landia.: 3 I.D.
	Slot/GauzeLength
	Set between 1/9 ft. and 12.3 ft.
	9 STATIC WATER LEVEL 3 X 18 mipper
	10 PUMPING LEVEL below land surface
	50 ft. after 2 hrs. pumping 10 g.p.m.
	ft. afterhrs. pumpingg.p.m.
	11 WATER QUALITY in Ports Per Million:
	Iron (Fe)Chlorides (CI)
	Hardness
	12 WELL HEAD COMPLETION: In Approved Pit
	Pitless Adopter 212" Above Grade
	13 GROUTING: Well Grouted? Yes K No
	Material: Neat Cement
C 10 7107	Depth: Fromft. toft.
(5)	Negrest Source of possible contamination
12.00	50 feetDirectionType
	Well disinfected upon completion ☐ Yes ☐ No 15 PUMP:
1283 / 3/	Manufacturer's Name Mysse
	Model Number 5 F 5 HP 12
Course to	Length of Drop Pipe / ft. capacity / O.P.M. Type: Submersible
	Jet Reciprocating
16 Remarks, elevation, source of data etc.	17 WATER WELL CONTRACTOR'S CERTIFICATION: This well was drilled under my jurisdiction and this report is true
CONTRACTOR DV. PTZ	to the best of my knowledge and belief.
*. CRRECTED BY:	REGISTERED BUSINESS NAME REGISTRATION NO.
**ADDITION BYS	Address 7686 aligned Richmond
	Signed Server Reules Date 5-76-67



MAR 05 1979

RTE MOUILLEE S.G.A.

February 10, 1979

Michigan Water Resources Commission Water Quality Division 4. 0. Bon 30028 Lausing, Michigan 48909

Attn: John M. Bohunsky, Regional Engineer

Dear Mr. Bohansky:

In accordance with provisions of Part II, paragraph B, 8, of our NPDES Permit # MI 0023833 under which we are presently operating, this is to advise you of conditions leading to our collection system and this treatment plant receiving a large amount of #2 Diesel Fuel.

A broken delivery line from a 100,000 gallon storage tank located on the property of Grand Trunk Western Railroad ruptured, and the lost oil entered a catch basin - only a few feet from the break and was carried through our remote lift station to our plant. We discovered this problem about 8:00 P.M. of February 7th, and had it traced to the railyards by midnight. Unfortunately, the railroad personnel were unable to locate the area of the leak, and initially denied being the source. The broken line was finally identified as the source about 5:30 A.M. of the 8th. Contact was made with Rick Lumpgren of DNR and officials of Grand Trunk, and arrangements to remove the oil, cily sewage and a significant amount of oily soum resulting from a combination of the diesel fuel with trace amounts of lat in paper coating (reference mine of February 3, 1979 to yourself) were made.

A licensed industrial hauler from Coruna Ontario, Canada was contacted. He removed approximately 1,400 U.S. gullens of #2 diesel fuel from our lift station and 11,600 gallows of oil and oily waste from our plant for disposal. This was accomplished by 3:00 P.M. of February 9th. The oil was carefully contained in our lift station and primary process, and has not had a noticeable effect as yet on our secondary process. To the best of our knowledge, no oil was discharged to the St. Clair River. Grand Trunk has accepted responsibility for costs incurred by us, and has repaired the leak.

Very truly yours,

58/6/1 := 700	
Les Holles	•
	:
-	
	
E Ad	
	:
·	
	APPROX, 50,000 PEBPLE,
	IN PINEGROVE PARIC, THE
	THE COCATION OF THE INT
	CAKE HURDY THEY EXTEND
	APPROXIMATELY "/A MILE SOU
TAKES ARE CLOSE TOGETHER.	MUNICIPAL WELLS, THE IN
T. CLAIR RIVER AND ND	SURFACE INTAKES FROM THE S
AT THE CITY HAS (a)	MP. GOSS STATED TH
MITTER MATTER SYSTEM	SUBJECT: PORT HURON MI
. T430 S	PORT HUROW CITY WATE
	SUPERINTENDENT
64009 - L86 (E1E) 3NOH	CONTACT LEONARD 6055
7650	USIA FLAM SI AH BILE
	THE 10:00 HIL
TDD # 65-8303-03C	_58/6/1 31140
56065050 Q ZW	/ -/
24894510 BISUM O AN	V7.1.22 21.2.
and the state of t	4